

## detailed room inspection results

building 2232 Piedmont

room general

inspection date 9/22/2008

occupant(s) overall comments

Y= yes (satisfactory)  
N=no (needs correction)  
na= not applicable

Safety evaluation	correction dates
electrical grounding <input checked="" type="checkbox"/> Y <input type="checkbox"/> N <input type="checkbox"/> na	
powerstrips <input type="checkbox"/> Y <input type="checkbox"/> N <input type="checkbox"/> na	
furniture bolting <input type="checkbox"/> Y <input type="checkbox"/> N <input type="checkbox"/> na	
trip/slip hazards <input type="checkbox"/> Y <input type="checkbox"/> N <input type="checkbox"/> na	
ergonomic evals <input type="checkbox"/> Y <input type="checkbox"/> N <input type="checkbox"/> na	
door latches <input type="checkbox"/> Y <input type="checkbox"/> N <input type="checkbox"/> na	

### notes and questions

Need batteries on emergency noisemaker to test, need to buy 4 more. Need to have fire and emergency assembly drill. Need to post hazard report forms somewhere and advertis their existence.

---

building 2224 Piedmont

room 26

inspection date 9/22/2008

occupant(s) Carl Boe

Y= yes (satisfactory)  
N=no (needs correction)  
na= not applicable

Safety evaluation	correction dates
electrical grounding <input checked="" type="checkbox"/> Y <input type="checkbox"/> N <input type="checkbox"/> na	
powerstrips <input type="checkbox"/> Y <input checked="" type="checkbox"/> N <input type="checkbox"/> na	
furniture bolting <input checked="" type="checkbox"/> Y <input type="checkbox"/> N <input type="checkbox"/> na	
trip/slip hazards <input checked="" type="checkbox"/> Y <input type="checkbox"/> N <input type="checkbox"/> na	
ergonomic evals <input type="checkbox"/> Y <input type="checkbox"/> N <input type="checkbox"/> na	
door latches <input checked="" type="checkbox"/> Y <input type="checkbox"/> N <input type="checkbox"/> na	

### notes and questions

New surge protector on order.

---

building 2224 Piedmont

room 27

inspection date 9/22/2008

occupant(s) Magali Barbieri

Y= yes (satisfactory)  
N=no (needs correction)  
na= not applicable

Safety evaluation	correction dates
electrical grounding <input checked="" type="checkbox"/> Y <input type="checkbox"/> N <input type="checkbox"/> na	
powerstrips <input type="checkbox"/> Y <input checked="" type="checkbox"/> N <input type="checkbox"/> na	
furniture bolting <input checked="" type="checkbox"/> Y <input type="checkbox"/> N <input type="checkbox"/> na	
trip/slip hazards <input checked="" type="checkbox"/> Y <input type="checkbox"/> N <input type="checkbox"/> na	
ergonomic evals <input type="checkbox"/> Y <input type="checkbox"/> N <input type="checkbox"/> na	
door latches <input checked="" type="checkbox"/> Y <input type="checkbox"/> N <input type="checkbox"/> na	

### notes and questions

Surge protector on order. Replace heater.

---

## detailed room inspection results

building 2224 Piedmont

room 29

inspection date 9/22/2008

occupant(s) Lisa Yang, Dana Gleib, workstudy students

Y= yes (satisfactory)  
N=no (needs correction)  
na= not applicable

Safety evaluation	correction dates
electrical grounding <input checked="" type="checkbox"/> Y <input type="checkbox"/> N <input type="checkbox"/> na	
powerstrips <input checked="" type="checkbox"/> Y <input type="checkbox"/> N <input type="checkbox"/> na	
furniture bolting <input type="checkbox"/> Y <input checked="" type="checkbox"/> N <input type="checkbox"/> na	
trip/slip hazards <input checked="" type="checkbox"/> Y <input type="checkbox"/> N <input type="checkbox"/> na	
ergonomic evals <input type="checkbox"/> Y <input type="checkbox"/> N <input type="checkbox"/> na	
door latches <input checked="" type="checkbox"/> Y <input type="checkbox"/> N <input type="checkbox"/> na	

### notes and questions

Bolting on order, not completed. Bookcases need bungie cords

---

building 2224 Piedmont

room 30

inspection date 9/22/2008

occupant(s) Gretchen Donehower

Y= yes (satisfactory)  
N=no (needs correction)  
na= not applicable

Safety evaluation	correction dates
electrical grounding <input checked="" type="checkbox"/> Y <input type="checkbox"/> N <input type="checkbox"/> na	
powerstrips <input type="checkbox"/> Y <input checked="" type="checkbox"/> N <input type="checkbox"/> na	
furniture bolting <input checked="" type="checkbox"/> Y <input type="checkbox"/> N <input type="checkbox"/> na	
trip/slip hazards <input checked="" type="checkbox"/> Y <input type="checkbox"/> N <input type="checkbox"/> na	
ergonomic evals <input type="checkbox"/> Y <input type="checkbox"/> N <input type="checkbox"/> na	
door latches <input checked="" type="checkbox"/> Y <input type="checkbox"/> N <input type="checkbox"/> na	

### notes and questions

Surge protector on order. Picture on shelf needs securing or lowering

---

building 2224 Piedmont

room 31

inspection date 9/22/2008

occupant(s) Mary Anderson

Y= yes (satisfactory)  
N=no (needs correction)  
na= not applicable

Safety evaluation	correction dates
electrical grounding <input checked="" type="checkbox"/> Y <input type="checkbox"/> N <input type="checkbox"/> na	
powerstrips <input type="checkbox"/> Y <input checked="" type="checkbox"/> N <input type="checkbox"/> na	
furniture bolting <input checked="" type="checkbox"/> Y <input type="checkbox"/> N <input type="checkbox"/> na	
trip/slip hazards <input checked="" type="checkbox"/> Y <input type="checkbox"/> N <input type="checkbox"/> na	
ergonomic evals <input checked="" type="checkbox"/> Y <input type="checkbox"/> N <input type="checkbox"/> na	
door latches <input checked="" type="checkbox"/> Y <input type="checkbox"/> N <input type="checkbox"/> na	

### notes and questions

Surge protector on order. Some concern with curtain that drapes over outlets; apply fire retardant? Occupant's concerns with seismic safety are being brought up to Physical Plant/building renovation directors.

---

## detailed room inspection results

building 2224 Piedmont

room 32

inspection date 9/22/2008

occupant(s) Clara Mantini Briggs

Y= yes (satisfactory)  
N=no (needs correction)  
na= not applicable

Safety evaluation	correction dates
electrical grounding <input checked="" type="checkbox"/> Y <input type="checkbox"/> N <input type="checkbox"/> na	
powerstrips <input checked="" type="checkbox"/> Y <input type="checkbox"/> N <input type="checkbox"/> na	
furniture bolting <input type="checkbox"/> Y <input checked="" type="checkbox"/> N <input type="checkbox"/> na	
trip/slip hazards <input checked="" type="checkbox"/> Y <input type="checkbox"/> N <input type="checkbox"/> na	
ergonomic evals <input type="checkbox"/> Y <input checked="" type="checkbox"/> N <input type="checkbox"/> na	
door latches <input checked="" type="checkbox"/> Y <input type="checkbox"/> N <input type="checkbox"/> na	

### notes and questions

new bookshelves need bolting.  
Has requested ergonomic evaluation.

---

building 2224 Piedmont

room 33

inspection date 9/22/2008

occupant(s) Vacant

Y= yes (satisfactory)  
N=no (needs correction)  
na= not applicable

Safety evaluation	correction dates
electrical grounding <input checked="" type="checkbox"/> Y <input type="checkbox"/> N <input type="checkbox"/> na	
powerstrips <input type="checkbox"/> Y <input checked="" type="checkbox"/> N <input type="checkbox"/> na	
furniture bolting <input checked="" type="checkbox"/> Y <input type="checkbox"/> N <input type="checkbox"/> na	
trip/slip hazards <input checked="" type="checkbox"/> Y <input type="checkbox"/> N <input type="checkbox"/> na	
ergonomic evals <input type="checkbox"/> Y <input type="checkbox"/> N <input type="checkbox"/> na	
door latches <input checked="" type="checkbox"/> Y <input type="checkbox"/> N <input type="checkbox"/> na	

### notes and questions

Surge protector on order. Computer components temporarily stored in this room while mold remediation continues in basement; office is vacant for now.

---

building 2224 Piedmont

room 7

inspection date 9/22/2008

occupant(s) Demography servers

Y= yes (satisfactory)  
N=no (needs correction)  
na= not applicable

Safety evaluation	correction dates
electrical grounding <input checked="" type="checkbox"/> Y <input type="checkbox"/> N <input type="checkbox"/> na	
powerstrips <input checked="" type="checkbox"/> Y <input type="checkbox"/> N <input type="checkbox"/> na	
furniture bolting <input checked="" type="checkbox"/> Y <input type="checkbox"/> N <input type="checkbox"/> na	
trip/slip hazards <input checked="" type="checkbox"/> Y <input type="checkbox"/> N <input type="checkbox"/> na	
ergonomic evals <input type="checkbox"/> Y <input type="checkbox"/> N <input checked="" type="checkbox"/> na	
door latches <input checked="" type="checkbox"/> Y <input type="checkbox"/> N <input type="checkbox"/> na	

### notes and questions

undergoing mold remediation, no entry without hazard prevention equipment in place.

---

# detailed room inspection results

building 2232 Piedmont  
occupant(s) Seminar Room

room 100

inspection date 9/22/2008

Y= yes (satisfactory)  
N=no (needs correction)  
na= not applicable

Safety evaluation	correction dates
electrical grounding <input checked="" type="checkbox"/> Y <input type="checkbox"/> N <input type="checkbox"/> na	
powerstrips <input checked="" type="checkbox"/> Y <input type="checkbox"/> N <input type="checkbox"/> na	
furniture bolting <input checked="" type="checkbox"/> Y <input type="checkbox"/> N <input type="checkbox"/> na	
trip/slip hazards <input checked="" type="checkbox"/> Y <input type="checkbox"/> N <input type="checkbox"/> na	
ergonomic evals <input type="checkbox"/> Y <input type="checkbox"/> N <input checked="" type="checkbox"/> na	
door latches <input type="checkbox"/> Y <input type="checkbox"/> N <input checked="" type="checkbox"/> na	

## notes and questions

Fire extinguisher has been relocated to just outside of door

---

building 2232 Piedmont

room 101A

inspection date 9/22/2008

occupant(s) main entryway

Y= yes (satisfactory)  
N=no (needs correction)  
na= not applicable

Safety evaluation	correction dates
electrical grounding <input checked="" type="checkbox"/> Y <input type="checkbox"/> N <input type="checkbox"/> na	
powerstrips <input checked="" type="checkbox"/> Y <input type="checkbox"/> N <input type="checkbox"/> na	
furniture bolting <input type="checkbox"/> Y <input checked="" type="checkbox"/> N <input type="checkbox"/> na	
trip/slip hazards <input checked="" type="checkbox"/> Y <input type="checkbox"/> N <input type="checkbox"/> na	
ergonomic evals <input type="checkbox"/> Y <input type="checkbox"/> N <input checked="" type="checkbox"/> na	
door latches <input type="checkbox"/> Y <input type="checkbox"/> N <input checked="" type="checkbox"/> na	

## notes and questions

Furniture needs bolting. Mailboxes need to be bolted/wedged under mantle to prevent falling in earthquake.

---

building 2232 Piedmont

room 101B

inspection date 9/22/2008

occupant(s) Monique Verrier

Y= yes (satisfactory)  
N=no (needs correction)  
na= not applicable

Safety evaluation	correction dates
electrical grounding <input checked="" type="checkbox"/> Y <input type="checkbox"/> N <input type="checkbox"/> na	3/7/2008
powerstrips <input checked="" type="checkbox"/> Y <input type="checkbox"/> N <input type="checkbox"/> na	
furniture bolting <input type="checkbox"/> Y <input checked="" type="checkbox"/> N <input type="checkbox"/> na	
trip/slip hazards <input checked="" type="checkbox"/> Y <input type="checkbox"/> N <input type="checkbox"/> na	
ergonomic evals <input type="checkbox"/> Y <input type="checkbox"/> N <input type="checkbox"/> na	
door latches <input checked="" type="checkbox"/> Y <input type="checkbox"/> N <input type="checkbox"/> na	

## notes and questions

Taller furniture needs bolting. Is it possible to consolidate more wires under GAO desk? Items on top of shelves need to be removed.

---

## detailed room inspection results

building 2232 Piedmont

room 102

inspection date 9/22/2008

occupant(s) photocopy room

Y= yes (satisfactory)  
N=no (needs correction)  
na= not applicable

Safety evaluation correction dates

electrical grounding  Y  N  na  
powerstrips  Y  N  na  
furniture bolting  Y  N  na  
trip/slip hazards  Y  N  na  
ergonomic evals  Y  N  na  
door latches  Y  N  na

### notes and questions

move extra dolly next door (now dolly can stay, there is no next door to move it to for the moment)  
Legally required postings have been updated.

---

building 2232 Piedmont

room 102A

inspection date 9/22/2008

occupant(s) Liz Oszelcuk

Y= yes (satisfactory)  
N=no (needs correction)  
na= not applicable

Safety evaluation correction dates

electrical grounding  Y  N  na  
powerstrips  Y  N  na  
furniture bolting  Y  N  na  
trip/slip hazards  Y  N  na  
ergonomic evals  Y  N  na  
door latches  Y  N  na

### notes and questions

Furniture needs bolting. Floor is cleaner than it used to be.

---

building 2232 Piedmont

room 102B

inspection date 9/22/2008

occupant(s) Ellen Langer

Y= yes (satisfactory)  
N=no (needs correction)  
na= not applicable

Safety evaluation correction dates

electrical grounding  Y  N  na  
powerstrips  Y  N  na  
furniture bolting  Y  N  na  
trip/slip hazards  Y  N  na  
ergonomic evals  Y  N  na  
door latches  Y  N  na

### notes and questions

Furniture needs bolting.Boxes need to be removed from top of bookcases.

---

## detailed room inspection results

building 2232 Piedmont

room 103

inspection date 9/22/2008

occupant(s) Mike Hout

Y= yes (satisfactory)  
N=no (needs correction)  
na= not applicable

### notes and questions

carpeting to reduce noise is on order.

Safety evaluation correction dates

electrical grounding  Y  N  na  
powerstrips  Y  N  na  
furniture bolting  Y  N  na  
trip/slip hazards  Y  N  na  
ergonomic evals  Y  N  na  
door latches  Y  N  na

---

building 2232 Piedmont

room 202

inspection date 9/22/2008

occupant(s) Ron Lee

Y= yes (satisfactory)  
N=no (needs correction)  
na= not applicable

### notes and questions

Replace old heater with newer, 3-pronged version. Old useless wires have been removed.  
Bookcases need bungie cords.

Safety evaluation correction dates

electrical grounding  Y  N  na  
powerstrips  Y  N  na  
furniture bolting  Y  N  na  
trip/slip hazards  Y  N  na  
ergonomic evals  Y  N  na  
door latches  Y  N  na

---

building 2232 Piedmont

room 204

inspection date 9/22/2008

occupant(s) John Wilmoth

Y= yes (satisfactory)  
N=no (needs correction)  
na= not applicable

### notes and questions

File cabinets have been bolted to each other. Bookcases need bungie cords.

---

Safety evaluation correction dates

electrical grounding  Y  N  na  
powerstrips  Y  N  na  
furniture bolting  Y  N  na  
trip/slip hazards  Y  N  na  
ergonomic evals  Y  N  na  
door latches  Y  N  na

## detailed room inspection results

building 2232 Piedmont

room 206

inspection date 9/22/2008

occupant(s) Carl Mason

Y= yes (satisfactory)  
N=no (needs correction)  
na= not applicable

Safety evaluation correction dates

electrical grounding  Y  N  na  
powerstrips  Y  N  na  
furniture bolting  Y  N  na  
trip/slip hazards  Y  N  na  
ergonomic evals  Y  N  na  
door latches  Y  N  na

### notes and questions

Carl will try to connect component in closet directly to wall in office to avoid use of extension cord.  
File cabinet needs bolting.

---

building 2232 Piedmont

room 208

inspection date 9/22/2008

occupant(s) Kenneth Wachter

Y= yes (satisfactory)  
N=no (needs correction)  
na= not applicable

Safety evaluation correction dates

electrical grounding  Y  N  na  
powerstrips  Y  N  na  
furniture bolting  Y  N  na  
trip/slip hazards  Y  N  na  
ergonomic evals  Y  N  na  
door latches  Y  N  na

### notes and questions

Needs old heater replaced by 3-prong plug kind. New surge protector has been ordered. Some bookcases need bungie cords.

---

building 2232 Piedmont

room 209

inspection date 9/22/2008

occupant(s) Leora Lawton

Y= yes (satisfactory)  
N=no (needs correction)  
na= not applicable

Safety evaluation correction dates

electrical grounding  Y  N  na  
powerstrips  Y  N  na  
furniture bolting  Y  N  na  
trip/slip hazards  Y  N  na  
ergonomic evals  Y  N  na  
door latches  Y  N  na

### notes and questions

Surge protector has been ordered. Use of extension cords unsafe. Have put in order to get estimate for adding new electrical plug on other side of office.

---

## detailed room inspection results

building 2232 Piedmont

room 210

inspection date 9/22/2008

occupant(s) Jennifer Johnson-Hanks

Y= yes (satisfactory)  
N=no (needs correction)  
na= not applicable

Safety evaluation	correction dates
electrical grounding <input checked="" type="checkbox"/> Y <input type="checkbox"/> N <input type="checkbox"/> na	
powerstrips <input type="checkbox"/> Y <input checked="" type="checkbox"/> N <input type="checkbox"/> na	
furniture bolting <input type="checkbox"/> Y <input checked="" type="checkbox"/> N <input type="checkbox"/> na	
trip/slip hazards <input checked="" type="checkbox"/> Y <input type="checkbox"/> N <input type="checkbox"/> na	
ergonomic evals <input type="checkbox"/> Y <input type="checkbox"/> N <input type="checkbox"/> na	
door latches <input checked="" type="checkbox"/> Y <input type="checkbox"/> N <input type="checkbox"/> na	

### notes and questions

Surge protector on order. Should order new bookcases so they can be bolted with rest of furniture.

---

building 2232 Piedmont

room 212

inspection date 9/22/2008

occupant(s) Gene Hammel

Y= yes (satisfactory)  
N=no (needs correction)  
na= not applicable

Safety evaluation	correction dates
electrical grounding <input checked="" type="checkbox"/> Y <input type="checkbox"/> N <input type="checkbox"/> na	
powerstrips <input checked="" type="checkbox"/> Y <input type="checkbox"/> N <input type="checkbox"/> na	
furniture bolting <input checked="" type="checkbox"/> Y <input type="checkbox"/> N <input type="checkbox"/> na	
trip/slip hazards <input checked="" type="checkbox"/> Y <input type="checkbox"/> N <input type="checkbox"/> na	
ergonomic evals <input type="checkbox"/> Y <input type="checkbox"/> N <input type="checkbox"/> na	
door latches <input checked="" type="checkbox"/> Y <input type="checkbox"/> N <input type="checkbox"/> na	

### notes and questions

Census data on shelves over the desk should be moved to lower place. Mike suggests possibility of having them scanned (ask Jon Stiles) or could be put in storage next door with other census data?

---

building 2232 Piedmont

room 300

inspection date 9/22/2008

occupant(s) Attic/ Library

Y= yes (satisfactory)  
N=no (needs correction)  
na= not applicable

Safety evaluation	correction dates
electrical grounding <input checked="" type="checkbox"/> Y <input type="checkbox"/> N <input type="checkbox"/> na	
powerstrips <input type="checkbox"/> Y <input checked="" type="checkbox"/> N <input type="checkbox"/> na	
furniture bolting <input type="checkbox"/> Y <input checked="" type="checkbox"/> N <input type="checkbox"/> na	
trip/slip hazards <input checked="" type="checkbox"/> Y <input type="checkbox"/> N <input type="checkbox"/> na	
ergonomic evals <input type="checkbox"/> Y <input type="checkbox"/> N <input type="checkbox"/> na	
door latches <input checked="" type="checkbox"/> Y <input type="checkbox"/> N <input type="checkbox"/> na	

### notes and questions

Refrigerator has been moved and excess wires leading to 2nd floor offices have been removed. Poorly functioning fan has been replaced with better one. Desk to right of stairs needs floor lamp. Papers in storage rooms have been discarded, 4 bookcases have been removed and stored to reduce weight on attic floor. One surge protector has been ordered. Will request bungee cords for lower books as well as upper, as they would impede exit if they were to fall.

Continued concern over fire escape safety, split noticed on board near top.

---

## detailed room inspection results

building 2232 Piedmont

room B-1

inspection date 9/22/2008

occupant(s) Basement, computer room, central room

Y= yes (satisfactory)  
N=no (needs correction)  
na= not applicable

Safety evaluation	correction dates
electrical grounding <input checked="" type="checkbox"/> Y <input type="checkbox"/> N <input type="checkbox"/> na	
powerstrips <input type="checkbox"/> Y <input checked="" type="checkbox"/> N <input type="checkbox"/> na	
furniture bolting <input type="checkbox"/> Y <input checked="" type="checkbox"/> N <input type="checkbox"/> na	
trip/slip hazards <input checked="" type="checkbox"/> Y <input type="checkbox"/> N <input type="checkbox"/> na	
ergonomic evals <input type="checkbox"/> Y <input type="checkbox"/> N <input type="checkbox"/> na	
door latches <input checked="" type="checkbox"/> Y <input type="checkbox"/> N <input type="checkbox"/> na	

### notes and questions

One bookshelf still needs bolting. Power strips OK? Replace older if any left over. Bolt printer holder?

---

building 2232 Piedmont

room B-2

inspection date 9/22/2008

occupant(s) Emilio Zagheni

Y= yes (satisfactory)  
N=no (needs correction)  
na= not applicable

Safety evaluation	correction dates
electrical grounding <input type="checkbox"/> Y <input checked="" type="checkbox"/> N <input type="checkbox"/> na	
powerstrips <input checked="" type="checkbox"/> Y <input type="checkbox"/> N <input type="checkbox"/> na	
furniture bolting <input checked="" type="checkbox"/> Y <input type="checkbox"/> N <input type="checkbox"/> na	
trip/slip hazards <input checked="" type="checkbox"/> Y <input type="checkbox"/> N <input type="checkbox"/> na	
ergonomic evals <input type="checkbox"/> Y <input type="checkbox"/> N <input type="checkbox"/> na	
door latches <input type="checkbox"/> Y <input checked="" type="checkbox"/> N <input type="checkbox"/> na	

### notes and questions

Remove old heater so doesn't get used.

---

building 2232 Piedmont

room B-3

inspection date 9/22/2008

occupant(s) storage room

Y= yes (satisfactory)  
N=no (needs correction)  
na= not applicable

Safety evaluation	correction dates
electrical grounding <input checked="" type="checkbox"/> Y <input type="checkbox"/> N <input type="checkbox"/> na	
powerstrips <input type="checkbox"/> Y <input type="checkbox"/> N <input checked="" type="checkbox"/> na	
furniture bolting <input checked="" type="checkbox"/> Y <input type="checkbox"/> N <input type="checkbox"/> na	
trip/slip hazards <input checked="" type="checkbox"/> Y <input type="checkbox"/> N <input type="checkbox"/> na	
ergonomic evals <input type="checkbox"/> Y <input type="checkbox"/> N <input checked="" type="checkbox"/> na	
door latches <input type="checkbox"/> Y <input type="checkbox"/> N <input checked="" type="checkbox"/> na	

### notes and questions

## detailed room inspection results

building 2232 Piedmont

room B-4

inspection date 9/22/2008

occupant(s) Pablo Comellato, Sarah Zureich

Y= yes (satisfactory)  
N=no (needs correction)  
na= not applicable

### notes and questions

Safety evaluation correction dates

electrical grounding  Y  N  na  
powerstrips  Y  N  na  
furniture bolting  Y  N  na  
trip/slip hazards  Y  N  na  
ergonomic evals  Y  N  na  
door latches  Y  N  na

---

building 2232 Piedmont

room B-5

inspection date 9/22/2008

occupant(s) Pablo Comelatto/Sarah Staveteig

Y= yes (satisfactory)  
N=no (needs correction)  
na= not applicable

### notes and questions

Surge protector on order.  
Door latch needs fixing

Safety evaluation correction dates

electrical grounding  Y  N  na  
powerstrips  Y  N  na  
furniture bolting  Y  N  na  
trip/slip hazards  Y  N  na  
ergonomic evals  Y  N  na  
door latches  Y  N  na

---

building 2232 Piedmont

room B-6

inspection date 9/22/2008

occupant(s) Red room: several grad students

Y= yes (satisfactory)  
N=no (needs correction)  
na= not applicable

### notes and questions

Bookcase needs bungie cords

Safety evaluation correction dates

electrical grounding  Y  N  na  
powerstrips  Y  N  na  
furniture bolting  Y  N  na  
trip/slip hazards  Y  N  na  
ergonomic evals  Y  N  na  
door latches  Y  N  na

## detailed room inspection results

building 2232 Piedmont

room exterior

inspection date 9/22/2008

occupant(s) exterior

Y= yes (satisfactory)  
N=no (needs correction)  
na= not applicable

Safety evaluation correction dates

electrical grounding  Y  N  na  
powerstrips  Y  N  na  
furniture bolting  Y  N  na  
trip/slip hazards  Y  N  na  
ergonomic evals  Y  N  na  
door latches  Y  N  na

### notes and questions

Concern about security of emergency fire escape remains. Has been repaired somewhat, but still doesn't look like it will hold in case of major shifting. Split noted on one board of wood structure. Building termite report has been received, evidence of termites, post beetles and water damage to wood, need to meet with Physical Plant to discuss priorities. Police inspector has noted that a light on the north side of the building would be an aid to security but estimate was around \$1000.

---

building 2232 Piedmont

room 101A

inspection date 9/22/2008

occupant(s) "tea room"

Y= yes (satisfactory)  
N=no (needs correction)  
na= not applicable

Safety evaluation correction dates

electrical grounding  Y  N  na  
powerstrips  Y  N  na  
furniture bolting  Y  N  na  
trip/slip hazards  Y  N  na  
ergonomic evals  Y  N  na  
door latches  Y  N  na

### notes and questions

Dangerous floor lamp has been discarded, space heater should be moved back into room 101B to prevent casual users leaving it on. Fire extinguisher now visible from tea room. Old microwave and toaster oven without removable crumb tray should be replaced with newer and safer models.

---

building 2224 Piedmont

room 8

inspection date 9/22/2008

occupant(s) Demography computer storage/repair

Y= yes (satisfactory)  
N=no (needs correction)  
na= not applicable

Safety evaluation correction dates

electrical grounding  Y  N  na  
powerstrips  Y  N  na  
furniture bolting  Y  N  na  
trip/slip hazards  Y  N  na  
ergonomic evals  Y  N  na  
door latches  Y  N  na

### notes and questions

undergoing mold remediation, no entry without hazard prevention equipment in place. Furniture in temporary storage in Marchant Building.

---

## detailed room inspection results

building 2224 Piedmont

room 9

inspection date 9/22/2008

occupant(s) Demography storage

Y= yes (satisfactory)  
N=no (needs correction)  
na= not applicable

Safety evaluation correction dates

electrical grounding  Y  N  na  
powerstrips  Y  N  na  
furniture bolting  Y  N  na  
trip/slip hazards  Y  N  na  
ergonomic evals  Y  N  na  
door latches  Y  N  na

### notes and questions

undergoing mold remediation, no entry without hazard prevention equipment in place. Furniture in temporary storage in Marchant Building.

---

building 2232 Piedmont

room kitchen

inspection date 9/22/2008

occupant(s) kitchen

Y= yes (satisfactory)  
N=no (needs correction)  
na= not applicable

Safety evaluation correction dates

electrical grounding  Y  N  na  
powerstrips  Y  N  na  
furniture bolting  Y  N  na  
trip/slip hazards  Y  N  na  
ergonomic evals  Y  N  na  
door latches  Y  N  na

### notes and questions

need replacement latch for kitchen cupboard (hopefully historical), need to remove trip hazard door jamb.

---

building 2224 Piedmont

room 2nd floor

inspection date 9/22/2008

occupant(s) second floor hallway and closets

Y= yes (satisfactory)  
N=no (needs correction)  
na= not applicable

Safety evaluation correction dates

electrical grounding  Y  N  na  
powerstrips  Y  N  na  
furniture bolting  Y  N  na  
trip/slip hazards  Y  N  na  
ergonomic evals  Y  N  na  
door latches  Y  N  na

### notes and questions

Hallway needs better lighting options (difficult to turn on/off because switches not near landing, need source of light when power goes out for people to leave safely). Has been discussed in meeting with Physical Plant electricians. Anthropology discarded furniture needs removal (tall file cabinet especially).

---